What is the best CNC Plasma Cutting Machine for your business?

## CNC Plasma Cutting Machine Buying Guide

Requirements when trying to find the best CNC Plasma Cutter: The material you need to cut The thickness of the material The largest size of your raw material sheet The quality required of the cutting The next step for the cutouts

### Four Types of CNC Plasma Cutters for Sale







Suitable for small workshops and/or engineering companies for all kinds of general purpose cutting

#### Large Size CNC Plasma Cutter

Suitable for middle size engineering companies

#### **Ultimate CNC Plasma Cutter**

This market leading cutter provides you with high-definition cutting quality, from the thickest materials in the fastest time

## Plasma Cutting Thickness & Materials



When you choose the thickness, use **Pierce Thickness Value** to help you decide

If you cannot pierce through a metal place, you cannot cut

·		Mild Steel (Carbon Steel)			Stainless Steel		Aluminum	
	Plasma System	Vritually Dross-free	Pierce	Severance	Pierce	Severance	Pierce	Severance
Entry	DRUMBO CUT-100	3 mm	10 mm	18 mm	8 mm	15 mm	8 mm	15 mm
Standard	Powermax45	4 mm	12 mm	25 mm	10 mm	20 mm	10 mm	20 mm
	Powermax65	6 mm	16 mm	32 mm	12 mm	25 mm	12 mm	25 mm
	Powermax85	8 mm	20 mm	38 mm	16 mm	30 mm	16 mm	30 mm
	Powermax105	10 mm	22 mm	50 mm	17 mm	40 mm	17 mm	40 mm
Large	MAXPRO200	20 mm	32 mm	75 mm	25 mm	60 mm	25 mm	60 mm
Ultimate	HPR130XD	16 mm	32 mm	38 mm	20 mm	25 mm	20 mm	25 mm
	HPR260XD	32 mm	38 mm	64 mm	32 mm	50 mm	25 mm	50 mm
	HPR400XD	38 mm	50 mm	80 mm	45 mm	80 mm	38 mm	80 mm
	HPR800XD	38 mm	50 mm	80 mm	75 mm	160 mm	75 mm	160 mm

## Plasma Cutting Quality

Plasma cutting technology has been existing and continually improving for more than 30 years



Cutting with plasma system does not require pre-heating like oxy-fuel system The quality of plasma cutting is far better than flame oxy-fuel cutting



All our plasma system will cut stacked, painted or rusted metal, and any electrically conductive metal type such as stainless steel and aluminium

# CNC Plasma Cutter Components Recommendation

	Entry Level CNC	Standard CNC		Large CNC	Ultimate CNC	
and the state	Plasma Cutter	Plasma Cut	ter	Plasma Cutter	Plasma Cutter	
X-Axis Driving	Stepper Motor		Panasonic Servo Motor (Choose Servo Motor for more reliable performance)			
Y-Axis Driving	Single Stepper Motor	Twin Stepper Motor		Servo Motor		
		Mechanical THC				
Torch Height Control	Arc Voltage THC (Cl choose Mechanical	Hypertherm ArcGlide THC				
CNC Control System	FangLing F2100B CNC Machine Control System Hypertherm EDGE Pro					
Nesting Software	FastCam Software Hypertherm Pr Software				Hypertherm ProNest Software	
Cutting	Up to	Up to		Recomme 2500 ×	end and from 6000 mm	
Area Size	1500 × 3000 mm	2000 × 3000	mm	Up to 2500 × 11000 mm	Up to any size, fully customizable	
Working Area	Providing 1 meter of space on each side of the cutting area is enough to operate the CNC plasma cutting machine. More space is preferable for loading metal plate, especially when you load by forklift.					
Cutting Table	Flat Cutting Table, No CollectorNormal Table with collect drawer or Water TablePrice does not i recommend wat manufa		nclude cutting table, er table which will be cture locally			
Table	Water table is much better for plasma cutting. We do NOT provide Downdraft Cutting Table.					

#### Cut Speed Comparison with Oxyfuel on 12 mm Mild Steel



## The Gradient

Unless you are choosing the ultimate CNC Plasma Cutter which has Hypertherm True-Hole technology, you will have a gradient on the work piece

The gradient and kerf can be measured and compensated for in our CNC plasma control system and removed in secondary operations, for example: grinding

## The Dross

No plasma system will provide you with a dross-free cut, only virtually dross-free cut

Dross can be easily removed in secondary operation, for example: grinding as well



# Physical Limitations

All our CNC Plasma Cutters make use of both **220V home** electricity and **380V industry electricity** 

If you do not have 380V three-phase industry power on your premises, your best chance is to **utilize a phase converter** 

# 2 Types of Cutting Process

#### **Edge start**



This is done by starting a cut at the edge of your working material while cutting inwards A lead in and a lead out of the work piece Using an Edge start is generally preferred



The torch nozzle is aimed directly at a specific starting point on the work piece the cut cannot be done in such a sequential manner as with an Edge start

## **General Cutting Thickness Calculation**

Recommended Max Cutting Thickness	=
Pierce Capacity	=
Virtually Dross-free Cutting Capacity	=

<b>80%</b> ×	Severance	<b>Thickness</b>
50%×	Severance	Thickness

30% × Severance Thickness

When you purchase plasma cutter, use Pierce Capacity to match you required cutting thickness. You will use Pierce Start at some stage, if you cannot pierce through the metal plate, you cannot cut through the metal place. This will also insure you will have the plasma cutter capable of give you optimal cutting result every time.



To Know More, Visit: http://am.co.za/plasma